





JM 14






| | | | | | | | | | |
|-------|----|-------|-----|-------|-----|-------|-----|--------|----|
| 0013K | 1x | 0001K | 18x | 0018K | 12x | 0019K | 12x | 0002V | 8x |
| | | | | | | | | | |
| | | 8x40 | | | | | | 3,5x16 | |

| | | | | | | | | | |
|-------|----|-------|----|-------|-----|-------|-----|-------|-----|
| 0005V | 2x | 0011K | 1x | 0016K | 40x | 0001V | 24x | 0009K | 12x |
| | | | | | | | | | |
| 7x50 | | | | | | 4x16 | | | |


| | | | | | | | | | |
|-------|----|-------|----|-------|----|-------|-----|-------|-----|
| 0015K | 4x | 0014K | 6x | 0006K | 4x | 0004V | 10x | 0003V | 14x |
| | | | | | | | | | |
| A | | | | M4x10 | | M4x20 | | 3x16 | |

| | | | | | | | |
|-------|----|-------|----|-------|----|-------|----|
| 0017U | 5x | 0002K | 5x | 0060K | 4x | 0036K | 2x |
| | | | | | | | |
| | | | | | | B | |


| | |
|-------|----|
| 0024K | 4x |
|-------|----|




| | |
|-------|----|
| 0054K | 6x |
|-------|----|



1.)




| | |
|-------|-----|
| 0001K | 18x |
|-------|-----|




8x40

2.)




| | | | |
|-------|----|-------|----|
| 0002V | 8x | 0024K | 4x |
|-------|----|-------|----|



3,5x16

| | | | |
|-------|-----|-------|----|
| 0001V | 12x | 0014K | 6x |
|-------|-----|-------|----|



4x16

